Index

Nuclear Safety

Volume 11

The page range for each of the six issues of Vol. 11 is as follows:

No. 1, pages 1 to 106
No. 2, pages 107 to 184
No. 3, pages 185 to 282
No. 4 pages 283 to 364
No. 5, pages 365 to 434
No. 6, pages 435 to 538

3HK5S
corrosion by liquid Na in contact with 316 stainless steel, 50

A

Accelerators
health-physics training course on, 374
beam-safety considerations for Stanford Linear, 435–44
Accidents
(see also Occurrences)
conference session on model of reactor, 315–16
conference session on radiological consequences of reactor, 318, 320–21
loss-of-coolant in large light-water power reactors, instrumentation for monitoring of, 468–73
Advisory Committee on Reactor Safeguards
election of Chairman and Vice-Chairman for 1970, 342–43
member appointment, 171
membership, 342–43
Air cleaning
eleventh AEC conference on, 205
Altamaha, Georgia
tornado probability, 300
American Nuclear Society
conference on reactor operating experience, report on, 56–64
Animals
food chains of, concentration and turnover of radioisotopes in, 43–53
Antimony
behavior in Na coolants, 386–88
Argon
behavior in Na coolants, 380–81
Atomic Energy Commission
eleventh air cleaning conference, 205
Nuclear Materials Safeguards Division, Director appointment for, 516–17
policy on implementation of the National Environmental Policy Act of 1969, 345
public relations program on the environmental aspects of nuclear power, 365–69
Atomic Safety and Licensing Appeal Board
organization and functions of, 83–84

B

Barium
behavior in Na coolants, 386–88
Bibliographies
of current nuclear safety literature, 104, 183, 281, 363
Books
"Atmospheric Transport Processes. Part 1: Energy Transfers and Transformations", 184
"Code of Practice and Technical Appendices", review of, 401
"Environmental Contamination by Radioactive Materials", review of, 492
Bush, Spencer H.
elected Vice-Chairman of ACRS, 342–43

C

Cerium
behavior in Na coolants, 385
Cesium
behavior in Na coolants, 382–84, 386–87
Cimarron Uranium Plant
radiation exposure incident, 242–43
"Code of Practice and Technical Appendices"
availability, 401
Compliance Division, AEC
Director, appointment of, 343
Computers (digital)
application in reactor operations, conference session on, 56–62
Concrete
use of prestressed for reactor pressure vessels, 25–32
Conferences and meetings
(see also Symposia and Seminars)
Annual Information Meeting of ORNL Nuclear Safety Program, 24
Eleventh AEC Air Cleaning Conference, Richland, Washington, Aug. 31–Sept. 3, 1970, 205
First International Conference on Structural Mechanics in Reactor Technology, 538
on radiation protection, 431
on reactor operating experience by the ANS, 56–64
on reliability of mechanical components on systems for nuclear reactor safety, Risø, Sept. 24–26, 1969, 309–14
review of International Congress on the Diffusion of Fission Products, Saclay, France, Nov. 4–6, 1969, 315–20
Universities, National Laboratories, and Man's Environment, 106
Consolidated Edison Company, New York
commitment to nuclear power, 343–44

D

Diffusion equation (time dependant)
for neutrons in fast breeder reactors, review of methods for solving, 289–94
Dresser Atlas, Houston, Texas
radiation exposure of X-ray-machine operator, 152

E

Easton, New York
tornado probability, 300
Electric utility companies
role in nuclear safety research and development, 185–93
Environment
(see also National Environmental Policy Act of 1969)
contamination by radioactive materials, book on, 492
effect of nuclear industry, comments by the House Appropriations Committee, 514–15
effects of nuclear industry on, AEC's public relations program for, 365–69
effect of nuclear industry on, conference on, 106

F

Fission products
behavior in Na coolants, 379–89
diffusion of, review of International Congress on, 315–20
Fluid flow
pressure pulses produced in water channels by rapid heating, analysis of, 12–19
Food chains
concentration and turnover of radioisotopes in animal, 43–53

G

Giambusso, Angelo
appointed Director, Compliance Division, AEC, 343

This index was prepared by Theodore F. Davis of AEC's Division of Technical Information Extension, Oak Ridge, Tenn.

XUM

H

Health, Education, and Welfare Department
course on environmental health services, 449
Hendrie, Joseph M.
elected Chairman of ACRS, 342–43
House Appropriations Committee
comments on the environmental aspects of civilian nuclear power, 514–15
Hydraulic fracturing
liquid waste disposal by, 391–99

I

Indexes
permuted title, to "Nuclear Safety", 105, 183, 281, 314
Instrumentation
for monitoring loss-of-coolant accidents in large light-water power reactors, 468–73
International Atomic Energy Agency
symposium on biophysical aspects of radiation quality, 431
symposium on new developments in physical and biological radiation detectors, 378
Iodine
behavior in Na coolants, 380–82, 386–88

K

Kaufman, Warren J.
appointment to the ACRS, 171
Krypton
behavior in Na coolants, 380–81

L

Lanthanum
behavior in Na coolants, 385
Larson, Clarence
testimony on ^{3}H release from nuclear power plants before the JCAE, 167–68
Leukemia
late mortality risks from reactor accidents, 482–88
Licensing and regulations
(see also specific reactors, e.g., Reactors (Bell))
on control of radioactive effluents from light-water-cooled reactors, 345–46
proposed amendment to include codes and standards for systems and components of nuclear power reactors, 168–71
proposed changes in, 102–3, 180–81, 278–79, 360–61, 432–33, 536–37
Lumb, Ralph F.
appointment as Director, AEC Nuclear Materials Safeguards Division, 516–17

M

Magnaflux Corp., Chicago, Ill.
radiation exposure incident, 500–1
Massachusetts Institute of Technology
reactor safety courses, 179
Medicine
use of radioisotopes in, symposium on radiation dose and effects of, 475–81
Meteorology
variability of wind direction within the U. S., 34–39
Missiles
tornado generated, characteristics of, 302–3

N

National Environmental Policy Act of 1969
AEC policy on implementation of, 345
National Naval Medical Center, Bethesda, Maryland
radiation exposure incident, 242
Neutrons
time-dependent diffusion equation for fast breeder reactors, review of methods for solving, 289–94
Nitrogen-16
suppression in pool-type research reactors, comparison of Plexiglas-type and 80 gal/min jet-type diffuser devices for, 237–40
Nuclear facilities
radiation monitoring, guide for administration practices in, 39–42
Nuclear Materials Safeguards Division
Director, appointment of, 516–17
"Nuclear Safety"
cover design for, competition in, 327, 390, 467
permuted-title index to, 105, 183, 281, 314, 535
Nuclear Safety Information Center
bibliographies of current nuclear safety literature, 105, 183, 281, 363
information programs, 101, 162–63, 337, 509
state-of-the-art reports, 104, 182, 280, 362

O

Oak Ridge National Laboratory
automation of reactor control and safety systems at, 115–18
liquid waste disposal by hydraulic fracturing, 391–99
Nuclear Safety Program, annual information meeting of, 24, 481
Occurrences
(see also Accidents)
Cimarron Uranium Plant, 242–43
Connecticut Yankee Atomic Power Plant, 402
Dresden 1 Reactor, 151–52, 402
Dresden 2 Reactor, 500
Dresser Atlas, Houston, Texas, 152, 502
General Electric Test Reactor, Vallecitos, Calif., 65, 152, 328
Ginna 1 Reactor, 241–42, 328–29
Gulf General Atomic Incorporated, TRIGA-Mk F Reactor, 66
H. B. Robinson 2 Reactor, 501
Humboldt Bay Reactor, 66
Indian Point 1 Reactor, 153, 500
La Crosse Boiling Water Reactor, 64–65, 403, 499–500
Magnaflux Corp., Chicago, Ill., 500–1
MIT Reactor, 65
National Naval Medical Center, Bethesda, Md., 242
Nine Mile Point Nuclear Station, 241, 329, 403
Northrop Corporate Laboratories, TRIGA-Mk F Reactor, 65
N. S. Savannah Reactor, 65
Oak Ridge Research Reactor, 323–27
Oyster Creek Nuclear Power Plant, Unit 1, 150–51, 152, 402–3
Peach Bottom Reactor, Unit 1, 241
Penn State TRIGA Reactor, 151
Pittsburgh Testing Laboratory, 66, 242
Quaker Alloy Casting Co., Myerstown, Pa., 328
San Onofre Reactor, 153–54
Saxton Reactor, 500
Screwworm Eradication Laboratory, Mission, Texas, 243
Theodore R. Schwalin, Inc., 64
U. S. Geological Survey TRIGA-Mk 1 Reactor, 151
United States Radium Corp., Bloomsburg, Pa., 329
Yankee Reactor, 242

P

Pacific Northwest Laboratory
work transfer from Battelle Memorial Institute to Westinghouse, 260
Pittsburgh Testing Laboratory
radiation exposure incident, 242
receipt of unshielded radiographic exposure unit, 66
Projectiles
tornado generated, characteristics of, 302–3
Public relations
AEC's program for environmental aspects of nuclear power, 365–69

Q

Quaker Alloy Casting Company, Myerstown, Pennsylvania
radiation exposure incident, 328

R

Radiation detectors
IAEA symposium on new developments in physical and biological, 378
Radiation doses
computation of, 490–91
Radiation exposure
incident at Cimarron Uranium Plant, 242–43
incident at Dresser Atlas, Houston, Texas, 152, 502
incident at General Electric Testing Reactor, Vallecitos, Calif., 328
incident at Ginna 1 Reactor, 328–29
incident at Magnaflux Corp., Chicago, Ill., 500–1
incident at National Naval Medical Center, Bethesda, Md., 242
incident at Pittsburgh Testing Laboratory, 242
incident at Quaker Alloy Casting Co., Myerstown, Pa., 328
incident at Screwworm Eradication Laboratory, Mission, Texas, 243
incident at United States Radium Corp., Bloomsburg, Pa., 329
incident at Yankee Reactor, 242
Radiation monitoring
in nuclear facilities, guide for administrative practices in, 39–42
Radiation protection
beam-safety considerations at Stanford Linear Accelerator, 435–44
meeting on, 431
Radioactive materials
environmental contamination by, book on, 492

seminar on test requirements for packaging for the transport of, 538
Radioactive wastes
disposal in salt formations, selection of site for, 515–16
disposal in salt formations, status of investigations on, 130–40
liquid, disposal by hydraulic fracturing at ORNL, 391–99
treatment and disposal, progress summary of research and development projects on, 159–62, 333–37, 506–9
Radioisotopes
concentration and turnover in animal food chains, 43–53
medical applications of, symposium on radiation dose and effects of, 475–81
Radon
detection in containment buildings of Kansas State University TRIGA MARK II Reactor, 235–37
Reactor containment systems
development and application of ice-condenser concept, 215–22
research on spray systems for pressurized-water reactors, 223–33
Reactor control systems
at ORNL, automation of, 115–18
Reactor coolants
fission-product behavior in liquid Na, 379–89
Reactor Development and Technology Division, AEC
criteria and requirements for plant protection systems, 375–77
Reactor fuels
conference session on emission of fission products from, 315–16, 318–19
storage pools for spent, tornado considerations for, 303–7
Reactor Licensing Division, AEC
reorganization of, 265
Reactor operators
training of, conference session on, 57, 63–64
Reactor pressure vessels
site assemble of Monticello, 119–29
use of prestressed concrete for, 25–32
Reactor safety
courses, 19, 179, 474
design basis for protection systems, 20–24
equation of state for studying fast reactors, 550–61
program development for the LMFBR, 1–10
progress summary of research and development projects for fast reactors, 163–66, 337–42, 509–12
progress summary of research and development projects for gas-cooled reactors, 166–67, 342, 512–13
progress summary of research and development projects for water-cooled reactors, 67–83, 155–59, 244–60, 330–33, 404–19, 503–6
research and development on, role of utilities in, 185–93
systems approach to, 445–49
Reactor siting
study of variability of wind direction within the U. S. for, 34–39
Reactor Standards Division, AEC
reorganization of, 265
Reactors
accident models, conference session on, 315–16
accidents, radiological consequences, conference sission on, 318, 320–21
control and safety systems at ORNL, automation of, 115–18
operating experience, report on the 1969 ANS conference on, 56–64
protection systems, criteria and requirements for RDT, 375–77
reliability of mechanical components and systems in, review of Risø meeting on, 309–14
Reactors (Arnold)
licensing and regulations, 88, 172, 266–68, 347–48, 420, 517–18
Reactors (ATR)
operating experience, conference session on, 62
Reactors (Beaver Valley)
licensing and regulations, 88, 172, 268, 347–48, 420, 426, 518, 524
Reactors (Bell)
licensing and regulations, 88, 172, 268, 348, 420, 518
spent-fuel storage pool for, characteristics of, 304
tornado probability, 300
Reactors (Big Rock Point)
licensing and regulations, 92, 176, 272, 352, 424, 522
Reactors (boiling water)
protection instrumentation systems in, 206–13
safety, a systems approach to, 445–49
use of prestressed-concrete pressure vessels for, 26
Reactors (BONUS)
licensing and regulations, 92, 176, 272, 352, 424, 522
Reactors (Browns Ferry 1)
licensing and regulations, 86–88, 172, 268, 348, 420, 518
tornado-generated missiles at, consideration of, 303
tornado probability, 300
Reactors (Browns Ferry 2)
licensing and regulations, 86–88, 172, 268, 348, 420, 518
tornado-generated missiles at, consideration of, 303
tornado probability, 300
Reactors (Browns Ferry 3)
licensing and regulations, 86–88, 172, 268, 348, 420, 518
tornado-generated missiles at, consideration of, 303
tornado probability, 300
Reactors (Brunswick 1)
licensing and regulations, 88, 171–72, 177, 268, 348, 354, 420, 518
spent-fuel storage pool for, characteristics of, 304
tornado probability, 300
Reactors (Brunswick 2)
licensing and regulations, 88, 171–72, 177, 268, 348, 354, 420, 518
tornado probability, 300
Reactors (Bugey 1)
design of prestressed-concrete pressure vessel for, 27
Reactors (Calvert Cliffs 1)
licensing and regulations, 87–88, 94, 172, 268, 348, 420, 518
tornado probability, 300
Reactors (Calvert Cliffs 2)
licensing and regulations, 87–88, 94, 172, 268, 348, 420, 518
tornado probability, 300
Reactors (Connecticut Yankee)
failure of absorber-rod supports for, 402
failure of control-rod gripper coils for, 402
licensing and regulations, 92, 176, 267, 272, 352, 424, 522
tornado probability, 300
Reactors (Cook 1)
Reactors (Donald C. Cook 1)
design of ice-condenser containment system for, 218–20
licensing and regulations, 88, 172, 268, 348, 420, 518
tornado probability, 300
Reactors (Cook 2)
licensing and regulations, 88, 172, 268, 348, 420, 518
tornado probability, 300
Reactors (Cooper)
licensing and regulations, 88, 172, 268, 348, 420, 518
tornado probability, 300
Reactors (Crystal River 3)
licensing and regulations, 88, 172, 268, 348, 420, 518
tornado probability, 300
Reactors (CVTR)
licensing and regulations, 92, 176, 272, 352, 424, 522
Reactors (Davis–Besse 1)
licensing and regulations, 88, 94, 172, 268, 348, 420, 518
Reactors (Diablo Canyon 1)
licensing and regulations, 88, 172, 268, 348, 420, 518
Reactors (Diablo Canyon 2)
licensing and regulations, 88, 172, 177–78, 268, 348, 420, 518
Reactors (Dresden 1)
control-rod-drive drift, 151
failure of float switches for, 402
licensing and regulations, 92, 176, 268, 272, 352, 424, 522
startup delay, 151–52
tornado probability, 300
Reactors (Dresden 2)
licensing and regulations, 88, 94–95, 172, 178, 267–68, 348, 424, 522, 524–25
release of primary cooling water into containment vessel, 500
tornado probability, 300
Reactors (Dresden 3)
licensing and regulations, 88, 172, 268, 348, 420, 518, 525–26
tornado-generated missiles at, consideration of, 303
tornado probability, 300
Reactors (Dungeness B)
design of prestressed-concrete pressure vessel for, 27
Reactors (EBR-II)
licensing and regulations, 92, 176, 272, 352, 424, 522
Reactors (EBWR)
licensing and regulations, 92, 176, 272, 352, 424, 522
Reactors (EDF-3)
design of prestressed-concrete pressure vessel for, 27
Reactors (EDF-4)
design of prestressed-concrete pressure vessel for, 27
Reactors (Elk River)
licensing and regulations, 92, 176, 272, 352, 424, 522, 526
Reactors (Farley 1)
licensing and regulations, 519
Reactors (Farley 2)
licensing and regulations, 519, 526
Reactors (fast)
conference session on the behavior

XUM

and trapping of fission products in primary circuits and confinement vessels of, 317–20
core behavior under accident conditions, studies of, 195–202
operating experience, conference session on, 60
safety of, courses on, 179
safety of, equation of state for study of, 450–61
safety of, progress summary of research and development projects on, 163–66, 337–42, 509–12
Reactors (fast breeder)
neutron-diffusion equation for, review of methods for solving of time-dependent, 289–94
Reactors (fast sodium-cooled)
safety assessment in the United Kingdom, 283–88
Reactors (Fermi 1)
licensing and regulations, 92, 176, 267, 272, 274, 352, 354, 424, 522
Reactors (Fermi 2)
licensing and regulations, 89, 173, 269, 349, 421, 519
Reactors (FitzPatrick)
licensing and regulations, 89, 173, 269, 349, 354–55, 421, 426, 519
Reactors (Forked River 1)
licensing and regulations, 519, 526
Reactors (Fort Calhoun)
licensing and regulations, 89, 173, 269, 349, 421, 519, 526–27
tornado probability, 300
Reactors (Fort St. Vrain)
design of prestressed-concrete pressure vessel for, 27
licensing and regulations, 89, 173, 269, 349, 421, 519
tornado-generated missiles at, consideration of, 303
tornado probability, 300
Reactors (G-2)
design of prestressed-concrete pressure vessel for, 27
Reactors (G-3)
design of prestressed-concrete pressure vessel for, 27
Reactors (gas cooled)
safety of, progress summary of research and development projects on, 168–67, 342, 512–13
use of prestressed-concrete pressure vessels for, 25–32
Reactors (General Electric Testing, Vallecitos)
control-rod failure during shutdown scram check, 65, 152
personnel overexposure during shutdown maintenance, 328
Reactors (Ginna 1)
damaged gate valve, 241–42
licensing and regulations, 89, 95, 173, 272, 352, 424, 522
radiation exposure incident, 328–29
valve failures, 328–29
Reactors (Gulf General Atomic Incorporated, Advanced TRIGA-Mk F)
control-rod-drive failure, 66
Reactors (Hatch)
licensing and regulations, 89, 96, 173, 178, 269, 349, 421, 519
Reactors (Hinkley B)
design of prestressed-concrete pressure vessel for, 27
Reactors (Humboldt Bay)
control-rod withdrawal with switch in neutral, 66
licensing and regulations, 92, 176, 272, 352, 424, 522
Reactors (Hutchinson Island 1)
licensing and regulations, 89, 173, 269, 349, 355–56, 421, 426, 519, 527
Reactors (Indian Point 1)
boric acid injection system, improvements on, 153
cracking of primary water line, 500
licensing and regulations, 92, 176, 272, 352, 424, 522
tornado-generated missiles at, consideration of, 303
tornado probability, 300
Reactors (Indian Point 2)
licensing and regulations, 89, 173, 269, 89, 173, 269, 349, 421, 426, 519
tornado probability, 300
Reactors (Indian Point 3)
licensing and regulations, 89, 96–99, 173, 269, 349, 421, 519
spent-fuel storage pool for, characteristics of, 304
tornado probability, 300
Reactors (Indian Point 4)
licensing and regulations, 89, 173, 269, 349, 421, 519
tornado probability, 300
Reactors (Indian Point 5)
licensing and regulations, 89, 173, 269, 349, 421, 519
Reactors (Kansas State University TRIGA MARK II)
containment buildings of, contamination by Rn, 235–37
Reactors (Kewaunee)
licensing and regulations, 89, 173, 269, 349, 421, 519
Reactors (La Crosse)
calibration of nuclear instrument channels, problems with, 64–65
failure of pressure-control system, 499–500
leak in the No. 2 feedwater injection-nozzle safe end, 403
licensing and regulations, 92, 176, 272, 352, 424, 522
Reactors (light-water cooled)
control of radioactive effluents from, amendment to AEC regulations on, 345–46
loss-of-coolant accidents, instrumentation for monitoring of, 468–73
protection instrumentation systems in, 206–13
Reactors (Limerick 1)
licensing and regulations, 349, 356, 421, 519
Reactors (Limerick 2)
licensing and regulations, 349, 356, 421, 519
Reactors (LMFBR)
core behavior under accident conditions, studies of, 195–202
fission-product behavior in Na coolant of, 379–89
safety program for, 1–10
Reactors (Maine Yankee)
licensing and regulations, 89, 173, 269, 349, 421, 519
tornado probability, 300
Reactors (Malibu)
licensing and regulations, 89, 173, 269, 349, 421, 519
Reactors (Midland 1)
licensing and regulations, 89, 173, 269, 349, 421, 519, 527–29
Reactors (Midland 2)
licensing and regulations, 89, 173, 269, 349, 421, 519, 527–29
Reactors (Milestone Point 1)
licensing and regulations, 90, 173, 269, 274–75, 350, 356, 421, 520, 529–30
Reactors (Milestone Point 2)
licensing and regulations, 90, 173, 269, 350, 421, 426–27, 520
Reactors (MIT Research)
flow scram defeated by failure of recorder balancing motor, 65
Reactors (Monticello)
licensing and regulations, 90, 99, 174, 270, 275–76, 350, 356, 422, 427, 520, 530
pressure vessel for, site assembly of, 119–29
tornado-generated missiles at, consideration of, 303
Reactors (Newbold Island 1)
licensing and regulations, 90, 100, 174, 270, 350, 356, 422, 520
Reactors (Newbold Island 2)
licensing and regulations, 90, 100, 174, 270, 350, 356, 422, 520
Reactors (New Production)
licensing and regulations, 273, 353, 425, 523
Reactors (Nine Mile Point)
core spray nozzle for, leaks in, 329
licensing and regulations, 90, 100, 174, 273, 353, 425, 523, 530
slow control-rod insertion, 241
stress-corrosion cracking of core-spray-nozzle safe end, 403
tornado probability, 300
undesirable automatic scram reset found in scram circuit of, 241
Reactors (North Anna 1)
licensing and regulations, 90, 174, 270, 350, 422, 520
Reactors (North Anna 2)
licensing and regulations, 90, 174, 270, 350, 422, 520
Reactors (Northrop Corporate Laboratories TRIGA-Mk F)
control-rod-drive failure, 65
Reactors (N. S. Savannah)
control-rod-scram valve failure, 65
licensing and regulations, 273, 353, 425, 523
Reactors (Oak Ridge Research)
failure of emergency-cooling system for, 323–27, 502
Reactors (Oconee 1)
licensing and regulations, 90, 174, 270, 350, 422, 520
spent-fuel storage pool for, characteristics of, 304
tornado-generated missiles at, consideration of, 303
tornado probability, 300
Reactors (Oconee 2)
licensing and regulations, 90, 174, 270, 350, 422, 520
spent-fuel storage pool for, characteristics of, 304
tornado-generated missiles at, consideration of, 303
tornado probability, 300
Reactors (Oconee 3)
tornado-generated missiles at, consideration of, 303
tornado probability, 300
Reactors (Oldbury)
design of prestressed-concrete pressure vessel for, 27
Reactors (Oyster Creek 1)
control-rod insertion time, problems with, 150–51
control-rod-withdrawal problems, 402–3

XUM

licensing and regulations, 90, 174, 273, 353, 425, 523, 531
pressure regulator failure causing scram of, 152–53
Reactors (Palisades)
licensing and regulations, 90, 174, 270, 350, 356–57, 422, 427, 520
tornado-generated missiles at, consideration of, 303
tornado probability, 300
Reactors (Pathfinder)
licensing and regulations, 273, 353, 357–58, 425, 523
Reactors (Peach Bottom 1)
failure of fuel-element sleeves, 241
licensing and regulations, 273, 353, 425, 523
tornado probability, 300
Reactors (Peach Bottom 2)
licensing and regulations, 90, 174, 270, 350, 422, 520
tornado-generated missiles at, consideration of, 303
tornado probability, 300
Reactors (Peach Bottom 3)
licensing and regulations, 90, 174, 270, 350, 422, 520
tornado-generated missiles at, consideration of, 303
tornado probability, 300
Reactors (Penn State TRIGA)
improper seating of regulating rod, 151
Reactors (PFR)
fuel-element failure in, instrumentation for detection of, 286–87
Reactors (Pilgrim)
licensing and regulations, 90, 174, 270, 350, 422, 520
tornado-generated missiles at, consideration of, 303
tornado probability, 300
Reactors (Piqua OMR)
licensing and regulations, 273, 353, 425, 523
Reactors (Point Beach 1)
licensing and regulations, 90, 174, 270, 350, 422, 427–28, 520, 531–32
tornado-generated missiles at, consideration of, 303
tornado probability, 300
Reactors (Point Beach 2)
licensing and regulations, 90, 174, 270, 350, 422, 427–28, 520
tornado-generated missiles at, consideration of, 303
tornado probability, 300
Reactors (pool type)
^{16}N suppression systems, comparison of Plexiglas plate-type and 80 gal/min jet-type diffuser, 237–40
Reactors (power)
"Code of Practice and Technical Appendices", 401
decommissioning of, conference session on, 61
environmental aspects of, AEC's public relations program on, 365–69
environmental aspects of, comments by the House Appropriations Committee, 514–15
licensing, practical value issue, 516
operating experience, conference session on, 58–59, 63
protection systems, design basis for, 20–24
reliability of mechanical components and systems in, review of Risø meeting on, 309–14
sabotage, assessment of probability and consequences of, 107–13
safety of, role of utilities in research and development on, 185–93
symposium on progress in safety evaluation of, 463–67
systems and components of, proposed codes and standards for, 168–71
tornado considerations for, 296–307
tritium release from, Clarence Larson's testimony before the JCAE on, 167–68
Reactors (Prairie Island 1)
licensing and regulations, 90, 174, 270, 350, 422, 520
Reactors (Prairie Island 2)
licensing and regulations, 90, 174, 270, 350, 422, 520
Reactors (pressurized water)
containment, research on spray systems for, 223–33
protection instrumentation systems in, 206–13
use of prestressed-concrete pressure vessels for, 26
Reactors (Quad Cities 1)
licensing and regulations, 90, 174, 270, 350, 422, 520
tornado-generated missiles at, consideration of, 303
tornado probability, 300
Reactors (Quad Cities 2)
licensing and regulations, 90, 174, 270, 350, 422, 520
tornado-generated missiles at, consideration of, 303
tornado probability, 300
Reactors (Rancho Seco)
licensing and regulations, 91, 174, 270, 351, 422, 520
Reactors (research)
(see also Reactors (test))
operating experience, conference session on, 58, 61, 63
Reactors (Robinson 2)
licensing and regulations, 91, 174, 270, 351, 422, 428–29, 520, 532
pipe failure, 501
Reactors (Russellville)
licensing and regulations, 91, 174, 270, 351, 422, 521
tornado probability, 300
Reactors (Salem 1)
licensing and regulations, 91, 175, 271, 351, 423, 521
Reactors (Salem 2)
licensing and regulations, 91, 175, 271, 351, 423, 521
Reactors (San Onofre 1)
boric acid injection system failure, 153–54
coolant-temperature anomalies, 142–50
licensing and regulations, 273, 353, 425, 523
Reactors (San Onofre 2)
licensing and regulations, 521, 532–33
Reactors (San Onofre 3)
licensing and regulations, 521, 532–33
Reactors (Saxton)
licensing and regulations, 273, 353, 425, 523
release of radioactive gases to the atmosphere, 500
Reactors (Seabrook)
licensing and regulations, 91, 175, 178, 271, 351, 423, 521
Reactors (Seala 1)
licensing and regulations, 175, 178, 271, 351, 423, 521, 533
Reactors (SEFOR)
licensing and regulations, 91, 100–1, 175, 273, 276, 353, 425, 523
Reactors (Sequoyah 1)
licensing and regulations, 91, 175, 271, 351, 358, 423, 429, 521
Reactors (Sequoyah 2)
licensing and regulations, 91, 175, 271, 351, 358, 423, 429, 521
Reactors (Shippingport 2)
licensing and regulations, 273, 353, 425, 523
tornado probability, 300
Reactors (Shoreham)
licensing and regulations, 91, 175, 271, 276–77, 351, 358–59, 423, 429, 521
Reactors (SRE)
licensing and regulations, 273, 353, 425, 523
Reactors (Surry 1)
licensing and regulations, 91, 175, 271, 351, 423, 521
tornado probability, 300
Reactors (Surry 2)
licensing and regulations, 91, 175, 271, 351, 423, 521
tornado probability, 300
Reactors (Susquehanna)
tornado probability, 300
Reactors (test)
(see also Reactors (research))
operating experience, conference session on, 57, 62–63
Reactors (thermal)
conference session on the behavior and trapping of fission products in primary circuits and confinement vessels of, 316–17, 319
Reactors (Three Mile Island 1)
licensing and regulations, 91, 175, 271, 351, 423, 521, 533
tornado probability, 300
Reactors (Three Mile Island 2)
licensing and regulations, 91, 175, 179, 271, 351, 423, 521
tornado probability, 300
Reactors (TRIGA)
report of seminar of owners, 493–98
Reactors (Trojan)
licensing and regulations, 91, 175, 271, 351, 423, 521, 533–34
Reactors (Turkey Point 3)
licensing and regulations, 91, 175, 271, 351, 423, 429–30, 521
tornado probability, 300
Reactors (Turkey Point 4)
licensing and regulations, 91, 175, 271, 351, 423, 429–30, 521
tornado probability, 300
Reactors (U. S. Geological Survey TRIGA-Mk 1)
leakage of ^{85}Kr and ^{133}Xe through control-rod-cladding pinholes, 151
Reactors (University of Wisconsin Research)
^{16}N suppression systems, comparison of Plexiglas plate-type and 80 gal/min jet-type diffuser, 237–40
Reactors (Vermont Yankee)
licensing and regulations, 91, 175, 271, 277, 351, 423, 521
Reactors (VESR)
licensing and regulations, 273, 353, 425, 523
Reactors (water)
pressure pulses produced in coolant channels by rapid heating, analysis of, 12–19

Reactors (water cooled)
containment, development and application of ice-condenser system for, 215–22
safety of, courses on, 179
safety program plan for, report on, 369–74
safety of, progress summary of research and development projects on, 67–83, 155–59, 244–60, 330–33, 404–19, 503–6
Reactors (Wylfa)
design of prestressed-concrete pressure vessel for, 27
Reactors (Yankee)
licensing and regulations, 273, 353, 425, 523
radiation exposure incident, 242
Reactors (Zimmer 1)
licensing and regulations, 423, 430, 521
licensing and regulations, 423, 430, 521
Reactors (Zion 1)
licensing and regulations, 91, 175, 271, 351, 423, 521
tornado-generated missiles at, consideration of, 303
Reactors (Zion 2)
licensing and regulations, 91, 175, 271, 351, 423, 521
tornado-generated missiles at, consideration of, 303
Regulations
(see Licensing and regulations)
Reports
Compilation of U. S. Nuclear Standards (1969), ORNL-NSIC-76, 390
Supplementary Criteria and Requirements for RDT Reactor Plant Protection Systems, RDT C16-1T, review of, 375–77
"Water-Reactor Safety Program Plan", summary of, 369–74
Reports (state-of-the-art)
of NSIC, 280
Roddis, Louis H.
speech on the future of nuclear power, 260–62
Rubidium
behavior in Na coolants, 384, 386–88

S

Sabotage
of nuclear power plants, assessment of probability and consequences of, 107–13
Salt formations
radioactive waste disposal in, selection of site for, 515–16
radioactive waste disposal in, status of investigations on, 130–40
Screwworm Eradication Laboratory, Mission, Texas
radiation exposure incident, 243
Seminars
(see also Training courses)
on test requirements for packaging for the transport of radioactive materials, 538
Sodium coolants
fission-product behavior in, 379–89
Southern California Edison Company
commitment to nuclear power, 344–45
Standards
administrative practices for radiation monitoring in nuclear facilities, 39–42
reactor protection systems, 375–77
U. S. nuclear, publication by NSIC, 390
Stanford Linear Accelerator
beam safety considerations, 435–44
Strontium
behavior in Na coolants, 384–88
Symposia
(see also Conferences and meetings)
AEC series, availability, 364, 434
on biophysical aspects of radiation quality, 431
on new developments in physical and biological radiation detectors, 378
on progress in safety evaluation of nuclear power plants, 463–67
on radiation dose and effects of radioisotopes in medicine, 475–81

T

Tellurium
behavior in Na coolants, 386–88
Theodore R. Schwalin, Inc.
tritium contamination in painting building of, 64
Thyroid carcinoma
late morality risks from reactor accidents, 482–88
Thompson, Theos J.
speaking engagement at the annual information meeting of ORNL's Nuclear Safety Program, 24
Tornados
characteristics of, 296–301
effect on nuclear power plants, analysis of, 301–7
strike probability, 298–300
Training courses
(see also Seminars)
on environmental health services, 449
fast nuclear power-reactor safety, 179
on health-physics aspects of accelerators, 374
UKAEA Reactor Safety Course No. 10, 19
UKAEA Reactor Safety Course No. 11, 474
water-cooled power-reactor safety, 179
Tritium
release from nuclear power plants, Clarence Larson's testimony before the JCAE on, 167–68

U

United Kingdom
fast sodium-cooled reactors in, safety assessment of, 283–88
reactor safety courses, 19, 474
United States Radium Corporation, Bloomsburg, Pennsylvania
radiation exposure incident, 329
USA Standard N13.2-1969
review of, 39–42

W

Wastes
(see Radioactive wastes)
Winds
direction within the U. S., variability of, 34–39

X

X-ray machine
operator exposure from, 152
Xenon
behavior in Na coolants, 380–81

XUM